

ANNEXURE-A

ENCLOSURE TO BBJ NIT NO. BBJ/M&P/D-2051/SPARES-CHICAGO PNEUMATIC/3132/2021 DT. 23.02.2021

| Sl. No. | Description of items | Part No. | Unit | Qty. | Rate Per Unit Rs. P. |
|--------------------|---|------------|------|------|-------------------------|
| A | Spares for Chicago Pneumatic make Drill (CP 3270 Drill) | | | | |
| i | Pinion Gear | E0161608 | No. | 1 | |
| ii | Rotor | C1713680 | No. | 2 | |
| iii | Rotor Blade | H5025680 | No. | 8 | |
| iv | Ball Bearing | M5426056 | No. | 2 | |
| v | Ball Bearing | M5449680 | No. | 2 | |
| B | Spares for Chicago Pneumatic make Compressor (CPS 400, New) | | | | |
| i | Air Filter | 6211475400 | Set | 1 | |
| ii | Oil Filter | | No. | 1 | |
| iii | Hydraulic Filter | | No. | 1 | |
| C | Spares for Chicago Pneumatic make Impact Wrench- CP 610 | | | | |
| i | Dog release Spring | H3414761 | No. | 10 | |
| ii | Steel Ball | M6112412 | No. | 100 | |
| iii | Ball retained Pin | D1124761 | No. | 6 | |
| iv | Dog | C4602761 | No. | 3 | |
| v | Spring tension Pin | M5008761 | No. | 6 | |
| vi | Roller | D1121761 | No. | 22 | |
| vii | Spindle | D193761 | No. | 3 | |
| viii | Thrust Flange | D6512761 | No. | 6 | |
| ix | Retainer Ring | M4001761 | No. | 6 | |
| x | O Ring for reverse Valve | H0110005 | No. | 6 | |
| xi | Rotor Blade | H5010761 | No. | 18 | |
| xii | Retaining Ring | M4107761 | No. | 6 | |
| xiii | O Ringh | Q0104700 | No. | 12 | |
| xiv | Throttle Valve | D1211761 | No. | 6 | |
| xv | O Ring Retainer | H5605761 | No. | 6 | |
| xvi | Throttle Spring | H3524761 | No. | 12 | |
| xvii | Bearing Assy.(consists of 24, 25,26, 27 of 28 each) | Z8314761 | No. | 6 | |
| xviii | Anvil | C1401761 | No. | 2 | |
| xix | Needle Bearing | | Set | 2 | |
| xx | Socket - M 34 | | No. | 2 | |
| xxi | Socket - M 36 | | No. | 2 | |
| GST (as applicale) | | | | | Extra |

NOTES :-

- (a). HSN Code of above spares to be mentioned clearly
(b). Percentage of GST also to be specified.

(Tapas Sen)
Supervisor(M&P)