

SPARES REQUIRED FOR "FUJI" MAKE CORNER DRILL MACHINE (TYPE: F-32 RCR) as under :

Sl.No.	Description of Spares	Part No.	Catalogue Drg. No.	Qty	Unit
1	Bevel Pinion	D-027423	423	6	No.
2	Key	K-32.514	H04	8	No.
3	Spindle	D-027438-00	438	3	No.
4	Rotor Blade	D-026208-00	208	30	No.
5	Needle Bearing	NB-SC78	A-31	8	No.
6	Rotor	D-026207-00	207	4	No.
7	Ball Bearing	BB-6202	A-01	6	No.
8	Ball Bearing	BB-6203	A-02	6	No.
9	Ball Bearing	BB-608	A-03	6	No.
10	Ball Bearing	BB-6202	A-04	6	No.
11	Ball Bearing	BB-7206	A-06	6	No.
12	Packing Leather	D-027722-00	722	12	No.
13	No. 2 Pinion	D-027403-00	403	2	No.
14	Cylinder	D-026209-00	209	2	No.
15	Cylinder Upper Plate	D-026210-00	210	4	No.
16	Cylinder Lower Plate	D-008211-00	211	4	No.
17	Bearing Holder	D-027436-00	436	2	No.
18	Snap Ring	SR-515	G-01	12	No.
19	Packing A	D-028621-00	621	12	No.
20	Packing B	D-027622-00	622	12	No.
21	Packing C	D-027623-00	623	12	No.
22	Bevel Gear	D-027430-00	426	6	No.
23	Needle Bearing	NB-HMK3525	432	8	No.
24	No. 1 Pinion	D-026401-00	401	2	No.
25	No. 1 Gear	D-027402-00	402	2	No.
26	Key	K-3311	H-01	10	No.
27	Key	K-339.5	H-02	10	No.
28	Key	K-4415	H-03	10	No.
29	Key	K-5514	H-05	10	No.
30	PIN	P-46	B-33	6	No.
31	Spring PIN	SP-310	B-31	8	No.
32	Housing Lower Cover	D-027204-00	204	2	No.